THE FLUORIDE INFORMATION SERVICE

Page 1 of 2 on; FLUORIDATION; DOSING AND DOSING PLANT

<u>A Struggle With Titans</u> page;

30-1 doubts whether concentration could be maintained

Fluoridation and Truth Decay pages;

Peru	[photo]; fluoride lorry and workers in protective clothing emptying 5000 gallons of fluoride into Lake Youngs, Seattle
48-9	equipment breakdown in Jackson, Michigan
49-50	equipment breakdowns due to corrosion of metal parts, impossible to maintain l ppm
221	0,2 ppm range for Grand Rapids dosing

The Fluoride Question page;

131	opposition	from	water e	engineers
132	water eng	ineer	s "jol.	ly tired"

Fluoridation 1979 <u>Scientific Criticisms and Fluoride Dangers</u> pages;

59-62 the difficulty in controlling fluoride concentration <u>Fluoride \ The Aging Factor</u> pages:

Annapolis fluoride spill

12

THE FLUORIDE INFORMATION SERVICE

Page 2 of 2 on; FLUORIDATION; DOSING AND DOSING PLANT

Fluoride in Australia \ A Case to Answer pages;

39 1.7, 1.8 and 2.6 ppm found in Melton, Victoria 46 moves afoot to lower the fluoridation concentration

Fluoride \ The Freedom Fight pages;

85 crowds queue to use unfluoridated supply from standpipes 96 long term threefold overfeed covered up by authorities 150 "if the fluoridation apparatus had been run by a horse, the result would have been the same"

National Fluoridation News issues;

XIV 3 May-Jun 1968	fluoride feeder precautions
XXIII Apr-Jun 1977	Equipment not Foolproof
	Fluoride Feeders For Sale
XXIV 3 Jul-Sep 1978	blew up during inspection
XXX 2 Summer 84	Health Department Will Consider Lowering Fluoride Levels
	Flow Meters Malfunction
XXXI 2 Fall 85	Explosion in Illinois Injures Three